

# 12

## Tech Notes

| Section Outline  | Page |
|--|------|
| 12.1 PREVIOUSLY PUBLISHED TECH NOTES INCLUDED IN THIS MANUAL ..... | 12-2 |

**Disclaimer:** The information in this document was carefully prepared and is believed to be correct, but EASA makes no warranties respecting it and disclaims any responsibility or liability of any kind for any loss or damage as a consequence of anyone's use of or reliance upon such information.

## 12.1 PREVIOUSLY PUBLISHED TECH NOTES INCLUDED IN THIS MANUAL

### EASA TECH NOTES

| Number | Title  | Page of Manual |
|--------|--|----------------|
| 1      | Hoist Troubleshooting.....   | (Withdrawn)    |
| 2      | The Function of the Interpole in DC Machines .....   | 3-29           |
| 3      | Connecting the Variable-Speed Commutator Motor.....  | 2-174          |
| 4      | Frog-Leg Windings for DC Machines .....  | 3-49           |
| 5      | Dynamometer Testing Electric Motors.....   | 7-33           |
| 6      | New International Connection Diagrams for Foreign 6- and 12-Lead Wye-Delta Motors .....  | (Withdrawn)    |
| 7      | Suffixes to NEMA Frames .....  | 2-6            |
| 8      | Understanding Motor Efficiency and Power Factor (replaced with The Impact of Voltage and Frequency Variation on Motor Life and Performance).....             | 2-82           |
| 9      | TIG-Welded Commutator Connections .....  | 3-47           |
| 10     | Winding Connections for Multi-Mode Three-Phase Motors.....   | 2-164          |
| 11     | Voltage Stresses in Three-Phase, AC Motors (Replaced with: Voltage Stress: Not as Simple as It Sounds).....  | 2-217          |
| 12     | Conversion Factors for Lap and Concentric Windings .....   | 2-187          |
| 13     | Solid Round Magnet Wire Data.....  | 6-2            |
| 14     | The Commutator and Its Maintenance .....   | 3-41           |
| 15     | Some Aspects of Magnetic Centering Effects on Sleeve Bearing Induction Motors .....  | 10-98          |
| 16     | Guidelines for Maintaining Motor Efficiency During Rebuilding (Revised) .....  | 2-98           |
| 17     | Stator Core Testing.....   | (Withdrawn)    |
| 18     | Troubleshooting a DC Motor at the Job Site .....   | 3-53           |
| 19     | Lubrication of Rolling Bearings in Electric Machines.....  | (Withdrawn)    |
| 20     | Cause and Analysis of Anti-Friction Bearing Failures in AC Induction Motors (Now titled: The Cause and Analysis of Bearing Failures in Electric Motors)..... | 8-32           |
| 21     | Thrust Anti-Friction Bearings for Vertical Motors (Now titled: Understanding and Adjusting Thrust Rolling Bearing Systems for Vertical Motors).....          | 8-22           |
| 22     | Brushholders and the Performance of Carbon Brushes.....  | 3-33           |
| 23     | Testing of Squirrel Cage Rotors .....  | 7-30           |
| 24     | UL 1446 Systems of Insulating Materials .....  | 6-24           |
| 25     | Rewinding Inverter Duty Motors.....  | 2-220          |

| Number | Title  | Page of Manual |
|--------|--|----------------|
| 26     | Can Energy Efficient Motors Be Rewound Satisfactorily? (replaced with The Effect of Repair/Replace on Motor Efficiency)..... | 2-101          |
| 27     | The Cause and Analysis of Bearing and Shaft Failures in Electric Motors  |                |
|        | Bearing Failures.....  | 8-32           |
|        | Shaft Failures.....  | 10-102         |
| 28     | Assuring the Mechanical Integrity of Electric Motors.....  | 10-4           |
| 29     | Application Considerations of Pulse-Width Modulated Inverters.....   | 5-36           |
| 30     | Fabrication of Replacement Shafts For Electric Motors.....   | 10-120         |
| 31     | The Cause and Analysis of Stator and Rotor Failures in AC Induction Machines.....  | 2-119          |
| 32     | Standards for Dynamic Balancing.....   | 10-18          |
| 33     | Taking Data on Form-Wound Motors and Generators .....  | 2-233          |
| 34     | PWM Amplifiers .....   | 5-11           |
| 35     | Rewinding Form-Wound Motors and Generators (Now titled Rewinding Form-Wound Motors and Generators up to 5 kV).....           | 2-239          |
| 36     | Armature Banding With Fiberglass.....  | 10-94          |
| 37     | Interspersed Windings: What Are They? .....  | 2-152          |
| 38     | Repairing Sleeve Bearings.....   | 8-42           |
| 39     | Procedure Writing: It Takes A Little Time, But The Results Are Worth It (No longer included)                                 |                |
| 40     | An Analytical Approach to Solving Motor Vibration Problems .....   | 10-28          |
| 41     | Electric Motor Shaft Analysis.....   | 10-116         |
| 42     | Procedures for Checking End Play in Ball Bearing Machines.....   | 8-49           |
| 43     | Making and Installing a New Motor Shaft.....   | 10-124         |
| 44     | Guide for Procuring Form Wound Coils for Motors and Generators .....   | 2-237          |
| 45     | Servo Drives.....  | 5-27           |
| 46     | The (Potential) Pitfalls of Parallel Circuits .....  | 2-210          |
| 47     | Concentric-to-Lap / Lap-to-Concentric Conversions .....  | 2-176          |
| 48     | Squirrel Cage Rotor Testing (Never included in Technical Manual)   |                |
| 49     | Simple Troubleshooting of Amplifiers in the Field.....   | 5-20           |

(This page intentionally left blank.)